

Digital Pressure Gauge



Installation and Operating Instructions



This publication is not subject to any update service. Information contained in this publication was in effect at the time the publication was approved for printing and is subject to change without notice or liability. ZF Off-Highway Solutions Minnesota Inc. reserves the right to revise the information presented or to discontinue the production of parts described at any time.



⚠ WARNING

GENERAL

A failure resulting in injury or damage may be caused by excessive overpressure, excessive vibration or pressure pulsation, excessive instrument temperature, corrosion of the pressure containing parts, or other misuse. Consult ZF Off-Highway Solutions Minnesota Inc. before installing if there are any questions or concerns.

OVERPRESSURE

Pressure spikes in excess of the rated overpressure capability of the gauge may cause irreversible electrical and/or mechanical damage to the pressure measuring and containing elements. Fluid hammer and surges can destroy any pressure transducer and must always be avoided. A pressure snubber should be installed to eliminate the damaging hammer effects. Fluid hammer occurs when a liquid flow is suddenly stopped, as with quick closing solenoid valves. Surges occur when flow is suddenly begun, as when a pump is turned on at full power or a valve is quickly opened.

PRESSURE SURGES

Surges are particularly damaging to pressure gauges if the pipe is originally empty. To avoid pressure surges, fluid lines should remain full (if possible), pumps should be brought up to

power slowly, and valves opened slowly. To avoid damage from both fluid hammer and surges, a surge chamber should be installed. Symptoms of fluid hammer and surge's damaging effects:

- Digital Gauge exhibits large zero offset
- Digital Gauge pressure display remains constant regardless of pressure
- Error code is displayed on screen

FREEZING

Prohibit freezing of media in pressure port. Unit should be drained. (Mount in vertical position to prevent possible overpressure damage from frozen media.)

INSTALLATION

This procedure requires the use of a 27 mm (1 1/16 inch) hex wrench for tightening the instrument to the process connection. Apply Teflon tape or a suitable sealing compound to NPT threads of the gauge. Take using the wrench, tighten 1 turn beyond hand-tight or until a leak-proof seal has been achieved.

⚠ CAUTION

Tightening the product by grasping or putting a tool on the plastic housing can cause permanent damage to the product.

GENERAL INFORMATION

Keypad


1. Power On-Off / Enter 
2. Zero / Up Arrow / Tare  Tare
3. Menu Selection / Down / Backlight Arrow 
4. Key presses are **short**  less than 0.5 seconds or **long**  greater than 0.5 seconds



LCD DISPLAY

LCD functions

1. Five numerical digits for pressure display
2. Twenty segment pressure range bar graph - each segment equals 5% of range
3. Sleep and backlight timer systems
4. Maximum/minimum pressure and tare icons
5. Five character alpha-numeric digit display
6. Four segment battery life indicator
7. Negative pressure indicator



Note: Key presses designated as short (less than 0.5 sec) are indicated by "↶" ICON.

Key presses designated as long (greater than 0.5 sec.) are indicated by "⏪" ICON.

Turn the Gauge ON/OFF


Press  key to turn instrument ON/OFF. When initially turned ON, the display will momentarily show all LCD segments lit, product version and full scale range; the unit will then proceed automatically to the measurement mode.

Zero Function

Press . Upon release, the numeric display momentarily disappears and "ZERO" shows in alpha display, then returns to measurement mode. The pressure should now read 0. Zero value is stored in memory.

Note 1: A display message of "RLOCK" indicates that zero is more than $\pm 5\%$ from factory calibration. Zeroing is not possible.

Note 2: A message of "ZLOCK" indicates that zero lock function is activated.



Tare Function

Subtracts current pressure value from value displayed in measurement mode.

In measurement mode, apply desired pressure press **ZERO** , to enable the tare function. The display will quickly flash "TARE", then the "TARE" icon will be displayed and the pressure reading will blink. The unit should now read 0. Press **ZERO**  the TARE key ICON again to disable the function. The display will quickly flash "T OFF", then the "TARE" icon will disappear and the pressure reading will no longer be blinking. The unit will now return to measurement mode.



Programming

To enter menu mode

1. Press **MENU**  and release to proceed to programming mode.
2. Press , , to scroll through programmable menu options.
3. When desired option is reached press  to access that parameter.
4. If at any time you choose to EXIT the menu mode (or sub-menu mode) hold **MENU** . Your work will not be saved.

Programmable Parameters

Units of Measure

1. In menu mode, press , , to scroll to "UNITS", press .
2. Choose engineering units by scrolling , , until desired unit is displayed, "PSI, BAR, kg/cm, kPa, mPa, FtH₂O, InHg, cmHG, mmHg, customer defined units (CUSTU)".
3. Press  to select units and return to measurement mode.

NOTE: Custom units programming, see page 7.



Custom Units of Measure

Allows a user to define a custom unit of measure, user must enter the full scale value of the desired reading, which can be done as follows.

1. In Menu Mode press  ,   select "CUSTU" press .

2. Select decimal point location:

The alphanumeric display shall show "SELDP".

The first screen to appear will show all digits lit up as "5" and the right most decimal point will blink (5 5 5 5.5) unless the custom units feature had been used previously. If it had been used, the digits and decimal point position shall correspond to the last values set. Use the  ,   keys to move the decimal point to the left or the right. Once the decimal point is in the desired position, press  to lock it in place. When the key is released the display reads "DIGIT".

3. Choose full scale value:

The alpha numeric display shall show "DIGIT".

The next screen will continue to show all digits as "5", with the left most digit blinking and the decimal point fixed in the previously chosen position. However, if the custom units feature has been used previously, then the digits shall correspond to the last value. The decimal point remains at the location chosen in step 1. Press  ,   to change the value of the digit between 0-9.

Once the desired value is displayed, press the   button to lock it in place. Now the next digit to the right will begin blinking. Repeat this procedure for all 5 digits. When the   is pressed and released with the fifth digit flashing, the gauge will briefly display "DONE" then return to measurement mode and display "CUSTU" along with the numeric readings to signify that the feature is in use.

The user can optionally exit at any point before the enter key is pressed with   . If the user exits the menu by a   before completing step 2 or there is a menu timeout, then whatever the user entered will be lost.

NOTE: The custom units feature is not available with compound pressure ranges.

NOTE: The bar graph uses the factory default setting when custom units are used.

NOTE: The magnitude of the value entered when using the custom units feature can significantly increase the noise on the display, which can affect the zero and tare functions as well as the stability of the pressure reading displayed. If required, consult factory for recommended limitations on full scale input.

Maximum/Minimum

Displays maximum/minimum pressure values; this is initiated upon powering the unit or since the values were cleared.

1. When in menu mode press  ,   to scroll to "Max" (maximum display); this is indicated in small font to the left of the display's unit of measure.
2. To clear both Min and Max values, press and hold   .
3. Release of this key will leave you in menu mode. Use  ,   to continue scrolling through the menu options, OR hold,   to return to measurement mode.

NOTE: Clearing Minimum/Maximum values will reflect a blank display except for the associated Min/Max icon and battery indicator.

NOTE: The following actions will also clear min/max values. Power off, zero gauge function, tare function, field calibration function, units programming, update rate, or reset.

Timer

Controls how long the gauge will remain powered ON once the Power key  is pressed.

1. When in menu mode press  ,   to scroll until "TIMER" is displayed.
2. Press   .
3. Then, press  ,   to scroll through values. "NONE" designates that the gauge will remain ON until the power key  is pressed a second time. Any other value (1 min [default] / 5 min / 20 min), other than "NONE", will designate the duration of time this function will be in effect.
4. Press   to select desired value; timer icon will be shown on the display and the unit will display "DONE" then return to measurement mode.

Feature: Timer icon will flash 10 seconds prior to gauge shut down.



Light

Determines how long the back light will remain ON after any key is pressed in measurement or menu modes. **NOTE: The timer is reset with any key being pressed.**

1. While in menu mode, press ,  until "LIGHT" is displayed.
2. Press  for timer value to appear; "ON" refers to the back light remaining ON at all times unit is powered ON, "PRESS" designates that the back light is switched on/off by briefly pressing the backlight  whereas, "OFF" indicates the back light will never be illuminated. Selecting time values, "1 MIN" (default), "5 MIN", "20 MIN", will activate the backlight symbol on the LCD display for the designated minutes.
3. Press  to select back light time (display will briefly show "DONE") and return to measurement mode.

NOTE: In "PRESS" mode; factory has set 1 hour timer to save battery.

Feature: Back light indicator will blink 10 seconds prior to light shut off.



Update

Utilized to select the rate at which the displayed pressure value is updated on the screen. This function is used when rapid changes in pressure cause "flutter" in the display values; longer intervals will reduce the update rate and "average" the readings on such applications.

1. In menu mode, press ,  until "UPDAT" appears.
2. Press  to select.
3. Press ,  to select values for "1 SEC" (default), "500 MSEC", or "250 MSEC".
4. Press  to select value (display will briefly show "DONE") and return to measurement mode.

NOTE: Changing value to anything other than 1 sec may cause a slight zero offset, and it is recommended that the gauge be fully vented and re-zeroed before taking accurate readings. Also, battery life will be reduced by use of an update rate faster than 1 SEC.



Z-Lock

Utilized to prevent inadvertent re-zeroing of the instrument.

1. In Menu mode, press ,  until "ZLOCK" appears.
2. Press  to select.
3. Press ,  to select "L ON" or "L OFF" (default).
4. Press  to select value (display will briefly show "DONE") and return to measurement mode.

NOTE: If Z-Lock is activated, the gauge will display "ZLOCK" if zero is attempted.



Re-Calibration

Provides the user the ability to field calibrate the product. Original factory calibration is permanently retained in memory and can be recalled at any time.

1. In menu mode press ,  until "RECAL" appears; proceed to press .
2. Display will indicate "FACT" (factory) "FIELD" or "NEW" press ,  to scroll.
3. Pressing  while "FACT" (factory) is displayed will restore values of factory calibration.
4. Pressing  when "FIELD" is displayed will restore values from latest field calibration.
5. Pressing "Enter" key  when "NEW" appears will enter the recalibrate mode.
6. When "NEW" is displayed, press ; upon release, the display will flash "OK/ APPLY/REF/ PSI/ THEN/ PRESS/ ENTER/ TO/ START/ OR/ OTHER/ TO/ ABORT". Numeric display will read 0.00000. Vent sensor to atmospheric pressure, press  display will show "WAIT" and count down from 6 seconds then briefly display "CAL" then automatically go to next step.
7. Display flashes "APPLY/ REF/ PSI/ THEN/ PRESS/ ENTER/ TO/ START/ OR/ OTHER/ TO/ ABORT"; apply the full scale pressure in units of PSI indicated in numeric display to gauge. Press  display will show "WAIT" and count down from 6 seconds then briefly display "CAL" then automatically go to next step.
8. Display flashes "APPLY/ REF/ PSI/ THEN/ PRESS/ ENTER/ TO/ START/ OR/ OTHER/ TO/ ABORT"; apply the pressure indicated in numeric display to gauge and press  display will show "WAIT" and count down from 6 seconds then briefly display "GOOD" then exit into measurement mode, or

9. COMPOUND RANGE GAUGES ONLY REQUIRE ONE ADDITIONAL CALIBRATION POINT NEAR VACUUM.
10. Display flashes "APPLY/ REF/ PSI/ THEN/ PRESS/ ENTER/ TO/ START/ OR/ OTHER/ TO/ ABORT"; apply near vacuum of -14.000 PSI as indicated in numeric display to gauge and press , display will show "WAIT" and count down from 6 seconds then briefly display "GOOD" then exit into measurement mode.

NOTE: Recalibration is allowed only if test parameters are within ±7%. If outside this window, the display will indicate "CAL FAIL/ INPUT PRES TOO LOW (HIGH)/ PRESS ENTER TO RETRY/ PRESS OTHER TO ABORT".

NOTE: "FIELD" option appears only if gauge has been successfully field recalibrated.

Graph

Provides the user the ability to modify pressure values dictating the minimum/maximum indications over the twenty segment bar graph.

1. In menu mode press ,  until "GRAPH" appears; press  .
2. Display will indicate "CGOFF" (custom graph off) [default], "CG ON" (custom graph on), or "NEWCG" (new custom graph) press ,  to scroll.
3. To recall the last custom graph entered when "CG ON" is displayed press  . Display will briefly show "DONE" and return to measurement mode.
4. To reset bar graph to full scale range; when "CGOFF" is displayed press  . Display will briefly show "DONE", and return to measurement mode.
5. To enter a new custom bar graph; when "NEWCG" is displayed press  .



6. To program minimum graph percentage, the display will indicate 0 0 with the right digit flashing, the bottom most segment of the bar graph will flash, and the display will read "PCTFS" (percent full scale). Press ,  to scroll to a number 0-9. Press  to select that number. The left digit will now begin to flash. Press ,  to scroll to a number 0-9.  to select that number. The 2 digit number entered represents the percentage of full scale to be used as the low end of the graph (0-99%).

7. To program maximum percentage of full scale the display will indicate 1 0 0 with the right digit flashing, the upper most segment of the graph will flash, and the display will read PCTFS (percent full scale). Press ,  to scroll to a number 0-9. Press  to select that number. The left 2 digits will now begin to flash. Press ,  to scroll to a number 0-10. Press  to select that number. The number entered represents the percentage of full scale to be used as the high end of the graph.

NOTE: 100 is the highest and only possible 3 digit number. If the low number is equal to or larger than the high number, the unit will flash "REJECT" and it will exit back into the "GRAPH" sub-menu.

NOTE: Custom graph function is not available on vacuum and compound ranges.

NOTE: A display message "ULOCK" indicates that custom units are being used and bar graph minimum and maximum are set to the factory defaults.

Reset

Returns the product to the factory default values.

Preserves field calibration. Factory calibration can be restored in the "RECAL" menu.

1. In menu mode ,  until "RESET" appears on display's lower line;  .


Factory defaults pertain to units, timer, back light, update rate, zero lock.

Display will indicate "DONE" then gauge will switch to "OFF" condition.




Changing Batteries:

Grip knurled back cover and rotate counter-clockwise until the 'unlock' icon is in alignment with the arrow – this is on the housing at the base of the pressure connection.




Remove cover by pulling straight back and replace AA alkaline batteries accordingly; ensure that the batteries are in the proper polarity position.



For reattachment of cover, align the 'unlock' icon with the arrow, push cover straight in then turn clockwise until the arrow is in alignment with the 'Lock' icon.

NOTE: Reinstallation of the back cover may cause the unit to read negative pressure. This is a temporary issue as the internal case pressure will be relieved by the case vent and equalize with atmospheric pressure (90% of the offset will equalize within 1 minute, the remaining 10% may take up to 5 minutes).



Pressure Range

Proof

Pressure	Vac-2000 PSI	200%
% of Span	3000-5000 PSI	150%
	7500-25,000 PSI	120%

Burst

Pressure	Vac-2000 PSI	800%
# of Span	3000-5000 PSI	500%
	7500-25,000 PSI	300%

Ambient Operating

-20°C to 60°C (-4°F to 140°F)

Process Media

-20°C to 80°C (-4°F to 176°F)

Agency Approvals

CE EN 61326 (1998); CE EN 61326
Annex A (Heavy Industrial)
UL/cUL-61010-1 (pending)
RoHS compliant

Environmental Specifications

Temperature

Storage

Batteries removed
-20°C to 80°C (-4°F to 176°F)
Batteries installed
-20°C to 60°C (-4°F to 140°F)

Dimensions

